

Plant Manager

My Construction Company Ltd, Trinity House, New Road, Halesowen, West Midlands, B63 3HY
Telephone Number : 0121 773 6821 - Fax Number : 0121 766 6740

Owned Plant Repairs History

Plant Details

73

Plant Description : Excavator 360 Degrees Tracked 17t
Make : Daewoo
Model : S175lc-v
Registration Nr :

Plant Flt Nr : 4W543
Mfr Date :
Serial Nr : 50159A
Colour :
Weight :

| Date | Damage | Foreman | Repaired By | Cost | Covered |
|----------|---|---------|-----------------|-----------|---------|
| 02/03/06 | Replace Fuel Tank Top And Damage On Cab | | My Repairco Ltd | £260.65 | No |
| 27/07/06 | Door Not Stay Open Beak Broken Battery Failed | | My Repairco Ltd | £467.41 | No |
| 19/10/06 | Investigate Non Strarter Refit Track Change Battery Terminals | | My Repairco Ltd | £190.37 | No |
| 09/11/06 | Replace Beacon And Bracket | | My Repairco Ltd | £111.39 | No |
| 09/01/07 | Track Wear, Remove Track, Refurb, Replace Track Sprockets And Missing Guide, Tension | | My Repairco Ltd | £3,625.05 | No |
| 22/01/07 | Replace Fuel Transfer Pump And Strainer Check Valve. | | My Repairco Ltd | £530.86 | No |
| 25/04/07 | Drill Bolts Abnd Replace Catch, Supply New Eacon And Buld Fit New Pins To Quick Hitch | | My Repairco Ltd | £244.03 | No |
| 26/07/07 | Replace Roll Pins In Quick Hitch | | My Repairco Ltd | £1,450.00 | No |
| 17/08/07 | Replace Beacon | | My Repairco Ltd | £124.04 | No |
| 24/09/07 | Beacon Bracket, Colour Reversing Kit, | | My Repairco Ltd | £327.60 | |
| 26/10/07 | New Track Motor, Bearing News, Bolts, Sprockets | | My Repairco Ltd | £4,969.62 | |
| 30/11/07 | Refit Tracks, Checking Running Gear, Rectify Grease Leak Tension Tracks | | My Repairco Ltd | £161.98 | |
| 11/02/08 | Broken Beacon | | My Repairco Ltd | £138.27 | |
| 14/04/08 | Track Rollers Worn Out And Track Guide Repair Beacon And Hitch Pin Tension Tracks | | My Repairco Ltd | £2,008.71 | |
| 31/08/08 | Quick Hitch Ram Failed, Concrete Built Up In Hitch Caused Ram To Fail Rebuild And Fix | | My Repairco Ltd | £561.31 | |
| 23/09/08 | Fuel Leak, Rectify Electrical Fault, New Hose Assembly, Check Tracks | | My Repairco Ltd | £274.55 | |

Notes